

GELCAST PRODUCTS CARE AND MAINTENANCE GUIDE

USING UTOPIA GELCAST PRODUCTS

General care in preserving the beauty and functionality of Utopia Gelcast products can be as simple as wiping regularly with a damp cloth and a detergent based cleaner

To protect against stains, cuts and heat damage, pay careful attention to the information below.

CLEANING

Because Gelcast material is non-porous, liquids and stains remain on the surface so they can be removed.

We only recommend that you use warm soapy water or a solution of mild, non abrasive detergent to clean your Gelcast Product.

We also recommend you rinse off household chemicals immediately, clean surface with warm soapy water and wipe dry.



HARMFUL CLEANERS AND CHEMICALS TO AVOID

CHEMICAL INGREDIENT	SYNONYMOUS NAMES
Hydrochloric Acid	Muriatic Acid Hydrogen Chloride
Sulphuric Acid	Oleic Acid Oleum
Hydrofluoric Acid	Rust Remover
Phosphoric Acid	Rust Remover
Sodium Hydroxide	Caustic Soda Caustic
Pumice (abrasive)	

Also avoid harsh abrasive cleaners and bleach.

HEAT

Never place hot objects or heat producing appliances directly onto a Gelcast Basin or worktop.



Always use a heat shield, hot pad or trivet to avoid marking the surface.



If you are in any doubts as to how to care for your Gelcast Basin or Worktop, please contact your retailer or alternatively call Utopia customer services on **01902 406402**